United States of America

Department of Transportation—Hederal Aviation Administration

Supplemental Type Certificate

Number SA257680

This certificate, issued to

Kosola and Associates, Inc. 5601 Newton Road Albany, GA 31707

Added Notes at Surrender:

- Future unsafe conditions existing in the product can result in an airworthiness directive requiring correction of the unsafe condition before further flight. If there is no entity to comply with 14 CFR 21.99(a), Required design changes, the existence of an unsafe condition might result in permanently grounding of the aircraft.
- Beplacement parts might not be available in

the fature certifies that the change in the type design for the following product with the limitations

therefor as specified hereon meets the airworthiness requirements of Part

Civil Air

Regulations.

Original Product - Type Certificate Number: A6WE

Make: McDonnell Douglas

Model: DC-9 30 series

STC Surrender processed:

Approval by: Date: 7/23/2009

Description of Type Design Change: Installation of the Avicom Model 2010 Tape Reproducer System in accordance with Kosola Report KR-799, Rev. NC., dated June 3, 1989, or later FAA approved revision.

Limitations and Conditions This approval should not be extended to other aircraft of this model on which other previously approved modifications are incorporated unless it is determined by the installer that the interrelationship between this change and any of those other previous approved modifications will introduce no adverse effect upon the airworthiness of that airplane.

ex and the supporting data which is the basis for approval shall remain in effect until surrendered, suspended, revoked, or a termination date is otherwise established by the Administrator of the Gederal Aviation Administration.

Date of application:

April 28, 1989

Date reissued:

Date of issuance:

June 23, 1989

Date amended:

By direction of the Administrator

Acting Manager, Atlanta Aircraft Certification Office

(Title)

Any alteration of this certificate is punishable by a fine of not exceeding \$1,000, or imprisonment not exceeding 3 years, or both.